

HABS
OHIO,
77-AKRO,
50-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Stan Hywet Hall, Service Building/Gardener's House
714 North Portage Path
Akron
Summit County
Ohio

HABS No. OH-50-D

Jack E. Boucher, HABS Staff Photographer July 1982

OH-50-D-1 SERVICE BUILDING, FROM EAST

OH-50-D-2 SERVICE BUILDING, FROM EAST

The following rectified photographs were taken by Chambers and Chambers Architects of Medina, Ohio in 1982(?). The captions include the Chambers and Chambers identification numbers and dimensions between the targets visible in each photograph. The camera positions are keyed to arrows on plans filed with the field records.

<u>HABS No.</u>	<u>CAPTION</u>	<u>C & C No.</u>	<u>TARGET DIMENSIONS</u>	
			<u>HORIZ.</u>	<u>VERT.</u>
OH-50-D-3	STORAGE/WORK ROOM, NORTHEAST	SB-02	38'2"	out to out
OH-50-D-4	WORK ROOM, NORTHWEST	SB-01	10'	5'
OH-50-D-5	WORK ROOM, SOUTHEAST	SB-03	none	5'